

2009 fall

Phase Transformation of Materials

09.17.2009

Eun Soo Park

Office: 33-316

Telephone: 880-7221


Email: espark@snu.ac.kr

Office hours: by an appointment

Contents for previous class

Equilibrium in Heterogeneous Systems

In X^0 , $G_0^\beta > G_0^\alpha > G_1 \rightarrow \alpha + \beta$ 로 분리 \rightarrow 두상의 화학 포텐셜 일치



Contents for today's class

- Binary phase diagrams

1) Simple Phase Diagrams

2) Systems with miscibility gap

4) Simple Eutectic Systems

3) Ordered Alloys

5) Phase diagrams containing intermediate phases

1.5 Binary phase diagrams

1) Simple Phase Diagrams

가정: (1) completely miscible in solid and liquid.


(2) **Both are ideal soln.**

$$\Delta H_{mix}^L = 0 \quad \Delta H_{mix}^S = 0$$

(3) $T_m(A) > T_m(B)$

(4) $T_1 > T_m(A) > T_2 > T_m(B) > T_3$


Draw G^L and G^S as a function of composition X_B at T_1 , $T_m(A)$, T_2 , $T_m(B)$, and T_3 .



1.5 Binary phase diagrams

1) Simple Phase Diagrams


- 가정: (1) completely miscible in solid and liquid.
(2) Both are ideal soln.
(3) $T_m(A) > T_m(B)$
(4) $T_1 > T_m(A) > T_2 > T_m(B) > T_3$



1.5 Binary phase diagrams

2) Systems with miscibility gap


$\Delta H_{mix}^L = 0$ $\Delta H_{mix}^S > 0$



How to characterize G^S mathematically
in the region of miscibility gap between e and f ?

Ideal Solutions

$$G_2 = G_1 + \Delta G_{mix}$$




Regular Solutions

$$G = X_A G_A + X_B G_B + \underbrace{\Omega X_A X_B}_{\Delta H_{mix}} + \underbrace{RT (X_A \ln X_A + X_B \ln X_B)}_{-T\Delta S_{mix}}$$

Reference state

Pure metal $G_A^0 = G_B^0 = 0$

$$\Delta G_{mix} = \Delta H_{mix} - T\Delta S_{mix}$$



(c) $\Omega > 0$, high T


(d), $\Omega > 0$ low T

1.5 Binary phase diagrams

2) Systems with miscibility gap

$$\Delta H_{mix}^L = 0 \quad \Delta H_{mix}^S > 0$$

- When A and B atoms dislike each other, $\Delta H_{mix} > 0$
- In this case, the free energy curve at low temperature has a region of negative curvature, $\frac{d^2G}{dX_B^2} < 0$
- This results in a 'miscibility gap' of α' and α'' in the phase diagram



1.5 Binary phase diagrams

4) Simple Eutectic Systems $\Delta H_{mix}^L = 0$ $\Delta H_{mix}^S \gg 0$

- $\Delta H_m \gg 0$ and the miscibility gap extends to the melting temperature. (when both solids have the same structure.)




Fig 1.32 The derivation of a eutectic phase diagram where both solid phases have the same crystal structure. (After A.H. Cottrell, *Theoretical Structural Metallurgy*, Edward Arnold, London, 1955, ©Sir Alan Cottrell.)

(when each solid has the **different crystal structure.**)




Fig. 1.33 The derivation of a eutectic phase diagram where each solid phase has a different crystal structure. (After A. Prince, *Alloy Phase Equilibria*, Elsevier, Amsterdam, 1966.)


1.5 Binary phase diagrams

Eutectic Systems

The Pb-Sn system is characteristic of a valley in the middle. Such system is known as the **Eutectic** system. The central point is the Eutectic point and the transformation through this point is called Eutectic reaction: $L \rightleftharpoons \alpha + \beta$

Pb has a fcc structure and Sn has a tetragonal structure. The system has three phases: L, α and β .

Pb-Sn phase diagram



1.5 Binary phase diagrams

Solidification of Eutectic Systems

Alloy II:

At point I: Liquid

Solidification starts at eutectic point (where liquidus and solidus join)


At point 2: $L \rightarrow (\alpha + \beta)$ (eutectic reaction)

The amounts of α and β increase in proportion with time.



Solidification finishes at the same temperature.

At point 3: $\alpha + \beta$


Further cooling leads to the depletion of Sn in α and the depletion of Pb in β .



1.5 Binary phase diagrams



Nucleation of colonies of α and β laminates



Eutectic structure of intimate mix of α and β to minimise diffusion path

1.5 Binary phase diagrams

Solidification of Eutectic Systems

Alloy I:

At point 1: Liquid

Solidification starts at liquidus

At point 2: L+ α

The amount α \uparrow with \downarrow T

Solidification finishes at solidus


At point 3: α

Precipitation starts at solvus






At point 4: α + β

Further cooling leads to formation and growth of more β precipitates whereas Sn% in α decreases following the solvus.


Pb-Sn phase diagram



1.5 Binary phase diagrams



Precipitates in a Al-Si alloy;
(a) optical microscopy,
(b) scanning electron
microscopy of fracture surface



1.5 Binary phase diagrams

Solidification of Eutectic Systems

Alloy III:

At point 1: Liquid

Solidification starts at liquidus

At point 2: $L \rightarrow L + \alpha$ (pre-eutectic α)

The amount $\alpha \uparrow$ with $\downarrow T$

At point 3: $L \rightarrow (\alpha + \beta)$ (eutectic reaction)


Solidification finishes at the eutectic temperature

At point 4: $\alpha + \beta$ (pre-eutectic α + $(\alpha + \beta)$ eutectic mixture)







Further cooling leads to the depletion of Sn in α and the depletion of Pb in β .

The cooling curve of this alloy is a combination of the two cooling curves shown in slide 9.

Pb-Sn phase diagram




1.5 Binary phase diagrams









1.5 Binary phase diagrams




Solidification of Eutectic Systems

Can you describe the solidification process of alloy IV, including microstructure evolution, morphology of phases and cooling curve?



1.5 Binary phase diagrams








허탈

환희

집중

기쁨

놀람






부끄러움

무아지경

세심

고통

분노



황당

억울

난감

아름다움

반가움

1.5 Binary phase diagrams


3) Ordered Alloys $\Delta H_{mix}^L = 0$ $\Delta H_{mix}^S < 0$

가. $\Delta H_{mix} < 0 \rightarrow$ A atoms and B atoms like each other.

How does the phase diagram differ from the previous case?


나. What would happen when $\Delta H_{mix} \ll 0$?

\rightarrow The ordered state can extend to the melting temperature.



Ideal Solutions

$$G_2 = G_1 + \Delta G_{mix}$$




Regular Solutions

$$G = X_A G_A + X_B G_B + \Omega X_A X_B + RT (X_A \ln X_A + X_B \ln X_B)$$

Reference state

Pure metal $G_A^0 = G_B^0 = 0$

$$\Delta G_{mix} = \Delta H_{mix} - T\Delta S_{mix}$$



1.5 Binary phase diagrams

Intermediate Phase


* Solid solution

- random mixing
- entropy ↑
- negative enthalpy ↓


$$\Delta H_{mix}^S < 0$$

넓은 조성 범위

→ G ↓



intermediate phases: (a) for an intermetallic compound (b) for an intermediate phase with a wide



* Compound : AB, A₂B...

- entropy ↓
- covalent, ionic contribution.
- enthalpy more negative ↓

$$\Delta H_{mix}^S \ll 0$$

좁은 조성 범위

→ G ↓






Fig. 1.23 Free energy curves for intermetallic compound with a very narrow stability range, (a) stability range.




1.5 Binary phase diagrams

5) Phase diagrams containing intermediate phases



1.5 Binary phase diagrams


5) Phase diagrams containing intermediate phases



Cu-Zn Phase Diagram

Eutectoid and Peritectic Reactions

peritectic:
 $\gamma + L \rightleftharpoons \delta$




peritectic:
 $\delta + L \rightleftharpoons \epsilon$

eutectoid:
 $\delta \rightleftharpoons \gamma + \epsilon$

Eutectoid: one solid phase transforms into two other solid phases upon cooling

Peritectic: one solid and one liquid phase transform into another solid phase upon cooling

Peritectoid: two other solid phases transform into another solid phase upon cooling




The Iron–Iron Carbide (Fe–Fe₃C) Phase Diagram

In their simplest form, steels are alloys of Iron (Fe) and Carbon (C). The Fe-C phase diagram is a fairly complex one, but we will only consider the part up to around 7% carbon of the diagram.

Eutectoid reaction
 $\gamma \leftrightarrow \alpha + \text{Fe}_3\text{C}$

Eutectic reaction
 $L \leftrightarrow \gamma + \text{Fe}_3\text{C}$



912°C α (BCC) \leftrightarrow γ (FCC) \leftrightarrow δ (BCC) \leftrightarrow liquid Pure iron

Development of Microstructure in Iron - Carbon alloys

- Microstructure depends on composition (carbon content) and heat treatment.
- In the discussion below we consider slow cooling in which equilibrium is maintained.

Eutectoid steel

When alloy of eutectoid composition (0.76 wt % C) is cooled slowly it forms a lamellar or layered structure of α and cementite (Fe_3C). This structure is called **pearlite**.

Mechanically, pearlite has properties intermediate to soft, ductile ferrite and hard, brittle cementite.




the dark areas are Fe_3C layers, the light phase is α -ferrite


Microstructure of hypoeutectoid steel

Compositions to the left of eutectoid (0.022-0.76 wt % C) **hypoeutectoid** alloys

- *less than eutectoid* (Greek)
Hypoeutectoid alloys contain **proeutectoid ferrite** (formed above the eutectoid temperature) plus the **eutectoid pearlite** that contain **eutectoid ferrite** and **cementite**.




Proeutectoid α



Microstructure of hypereutectoid steel


Compositions to the right of eutectoid (0.76 - 2.14 wt % C) hypereutectoid alloys.

- *more than eutectoid* (Greek)



pearlite

Preeutectoid cementite



1.5 Binary phase diagrams

The Gibbs Phase Rule

In chemistry, Gibbs' phase rule describes the possible number of degrees of freedom (F) in a closed system at equilibrium, in terms of the number of separate phases (P) and the number of chemical components (C) in the system. It was deduced from thermodynamic principles by Josiah Willard Gibbs in the 1870s.

Gibbs phase rule

$$F = C + N - P$$

F: degree of freedom

C: number of chemical variables

N: number of non-chemical variables

P: number of phases


In general, Gibbs' rule then follows, as:

$$F = C - P + 2 \quad (\text{from } T, P).$$

From Wikipedia, the free encyclopedia

The Gibbs Phase Rule

For Constant Pressure,
 $P + F = C + 1$



① single phase
 $F = C - P + 1$
 $= 2 - 1 + 1$
 $= 2$

can vary T and composition independently

② two phase
 $F = C - P + 1$
 $= 2 - 2 + 1$
 $= 1$


can vary T *or* composition

③ eutectic point
 $F = C - P + 1$
 $= 2 - 3 + 1$
 $= 0$


can't vary T or composition

The Gibbs Phase Rule

Application of Gibbs phase rule:
For a binary system at ambient pressure:
 $C=2$ (2 elements)
 $N=1$ (temperature, no pressure)
For single phase: $F=2$: % and T
(a region)
For a 2-phase equilibrium: $F=1$:
% or T (a line)
For a 3-phase equilibrium: $F=0$, (invariant
point)




재료 설계



재료 설계

Menu of engineering materials



재 료 설 계 주 제 제 안

이번 학기에 깊이있게 조사해보고 싶은
재료 3 가지와 그 이유를 각 1 page 씩
정 리 하 여 24 일 까 지 제 출 하 시 오 .

Ex) stainless steel/ Carbon nanotube/
Bio-material/ Dendrimer etc.

The Gibbs Phase Rule

Degree of freedom (number of variables that can be varied independently)

= the number of variables – the number of constraints

- Number of phases : p , number of components : c ,
- # of controllable variable : composition $(c-1)p$, temperature : p , pressure : p
- # of restrictions :

$$(p-1)c \text{ from chemical equilibrium} \quad \mu_i^{\alpha} = \mu_i^{\beta} = \mu_i^{\gamma} = \dots = \mu_i^p$$

$$p-1 \text{ from thermal equilibrium} \quad T^{\alpha} = T^{\beta} = T^{\gamma} = \dots = T^p$$

$$p-1 \text{ from mechanical equilibrium} \quad P^{\alpha} = P^{\beta} = P^{\gamma} = \dots = P^p$$

- Number of variable can be controlled with maintaining equilibrium

$$f = (c-1)p + p + p - (p-1)c - (p-1) - (p-1) = c - p + 2$$

$$f = c - p + 2$$

- If pressure is constant : $f = (c-1)p + p - (p-1)c - (p-1) = c - p + 1$