

Chapter 9

One-piece Production in Practice



Seoul National University
Professor ILKYEONG MOON

© All rights reserved, 2013

CONTENTS

9.1 Requirements for one-piece production

9.2 Resistance to working standing up

9.3 Resistance to multi-skilling

9.4 Barriers to automation

9.5 Attaching castors

9.6 Smoothed production

9.7 An example

9.1 REQUIREMENT FOR ONE-PIECE PRODUCTION

- ❖ In the JIT system, *one-piece production* or *single-unit production* is the concept of having things flow smoothly through the factory one by one, like water, without any holdups.
- ❖ The workers must be multi-skilled operators.

9.1 REQUIREMENT FOR ONE-PIECE PRODUCTION

- ❖ There are three essential requirements for one-piece flow.
 - working standing up
 - multi-process handling by multi-skilled workers
 - automation
- ❖ Do not try to achieve perfection at once.

9.2 RESISTANCE TO WORKING STANDING UP

- ❖ Managers should explain why it is necessary to work standing up.


Necessity No. 1:

- On an assembly line, it is difficult to share the workload equally among the workers.
- An overlap zone can be established between neighboring operators.
- When the workers are working standing up, they can move in and out of this overlap zone freely.

9.2 RESISTANCE TO WORKING STANDING UP

Necessity No. 2:

- Working standing up is a fundamental prerequisite at the heart of TPS. Take cooking in kitchens as an example.



9.2 RESISTANCE TO WORKING STANDING UP

Necessity No. 3:

- Practice shows that working standing up can eliminate the waste and strain in individual workloads.
- It can bring a better productivity, which is the quantity that each operator can produce during normal working hours in one day.

9.2 RESISTANCE TO WORKING STANDING UP

Benefits of working standing up


- Moving around more is good exercise and makes workers feel healthier.
- The posture of workers can improve.
- Neighboring workers can help each other out, so they can match their work rate to the pace of the line.

9.2 RESISTANCE TO WORKING STANDING UP

- ❖ Many companies failed to introduce TPS because their employees refused to accept working standing up.
- ❖ Managers should explain the necessities and benefits of working standing up to the workers or union representatives.


9.3 RESISTANCE TO MULTI-SKILLING

- ❖ The first step is that each worker learns how to do some of the tasks in the processes immediately after or after his own process.



9.3 RESISTANCE TO MULTI-SKILLING

- ❖ The second step is to have the workers learn to operate different machines little by little.




- ❖ Resistance exists due to the workers who have pride and confidence in their professional skills in particular operations.

9.3 RESISTANCE TO MULTI-SKILLING

- ❖ The third step is to explain the need for multi-process handling.
 - In current market, a large variety of products in small quantities are the customers' needs.
 - A system in which a fixed quantity of items is made every month no longer meets these needs.
 - One-piece production, achieved by means of multi-process handling can do it.

9.4 BARRIERS TO AUTONOMATION

- ❖ Under multi-process handling, machines have to be able to carry out their processing tasks automatically and switch themselves off when they finish the tasks.



9.4 BARRIERS TO AUTONOMATION

- ❖ In Toyota, this type of automation is called *autonomation* or *automation with human intelligence*.
- ❖ It is indispensable for multi-process handling which requires the improvement of machines.
- ❖ The production engineering department plays an important role in TPS.

9.4 BARRIERS TO AUTONOMATION

- ❖ The production engineering department needs to devise mechanisms for two things.
 - First, make the machines stop automatically when they finished each processing task.
 - Second, make the machines stop automatically when anything goes wrong during tasks.

9.4 BARRIERS TO AUTONOMATION

- ❖ Take an electric hole-punching machine as an example.
- ❖ This machine is used to make two holes in the left-hand side of a stack of documents in order to file them in a binder.



9.4 BARRIERS TO AUTONOMATION




FIGURE 9.1


Separation of human operation from machine. (Adapted from Hirano, H. 1989. *100 Q&A for JIT Introduction*, Nikkan Kogyo Shinbun, p. 69, with partial revision.)

9.4 BARRIERS TO AUTONOMATION

- ❖ To take the automation a stage further, the following additional improvements would be added.
 - Automate the removal of the work piece after processing.
 - Automate the setting of the work piece on the machine.
 - Automate the machine so that it stops whenever a defective product is produced.

9.5 ATTACHING CASTORS

- ❖ With the castors attached to the bases, machines are movable at any time in response to requirements.
- ❖ This is a prerequisite for changing the layout of the machines.
- ❖ This is the first thing that ought to be done for one-piece flow.



9.5 ATTACHING CASTORS

- ❖ Machine modifications are needed to achieve the automation that allows the workers to leave their machines.
- ❖ The production engineering department plays an important role.
- ❖ These hardware improvements require a certain amount of additional expenditure.

9.6 SMOOTHED PRODUCTION

- ❖ Process-sequenced production implies multi-process handling.
- ❖ Set up separate lines (*cell lines* or *cell*) each of which makes a particular item.
 - The whole system is called *cellular manufacturing*.

9.6 SMOOTHED PRODUCTION

- ❖ When a large variety of models is being made, the number of cells for particular items can be large.
- ❖ The final assembly line should be a mixed-model line and the production must be smoothed.
- ❖ This minimizes the number of production lines and improves the investment efficiency.

9.6 SMOOTHED PRODUCTION

- ❖ There are three stages of mixed–model assembly.
 - Produce in sequence, lumping the total quantity of each model needed each month together.
 - Produce in sequence, lumping the average quantity of each model needed each day together.
 - Produce each model one unit at a time, matching the pace to the takt time of each model.

9.7 AN EXAMPLE

- ❖ Take a factory producing cabinets for use as flat-screen television stands as an example.
- ❖ When the factory used the *job-shop layout* (group and lay out the machines of the same type), there was a considerable amount of work-in-process.
- ❖ The factory switched to an arrangement of U-shaped lines and turned the final assembly line into a one-piece flow line.

9.7 AN EXAMPLE




FIGURE 9.2
Example of improved layout: U-shaped multi-process handling in TV cabinet plant.

