


TOWARD PRODUCTION: PROTOTYPE AND FULL- SCALE

Lalit Patil
University of Michigan


Product development process



Good design




Good design



Design satisfies requirements.
Will the final product be good enough?

Good design




- Final success also depends on
 - ▣ Materials selected
 - ▣ Manufacturing practices
 - ▣ Distribution practices
 - ▣ ...


Steps forward




Steps forward



Steps forward



Steps forward



Steps forward



Bill Of Materials (BOM)

A **structured** list of the **materials, parts, assemblies** and their respective **quantities** that **define** a product.

Example




**Ladder-back
chair**

BOM: Subassemblies and components



Ladder-back chair



Bill Of Materials



Ladder-back chair

Item No	Sub-assembly	Intermediate	Purchase Items	Units	Cost (\$)	Source
1	Seat subassembly (1)	Seat frame (1)	Seat frame boards	4	0.55	USA
		Seat cushion		1	1.56	India
2	Ladder-back subassembly (1)	Back legs		2	0.45	China
		Back slats		4	0.35	China
3			Front legs	2	1.10	USA
4			Leg supports	4	0.35	USA

BOM in your project

- Develop BOM
 - ▣ determine components
 - ▣ determine subassemblies

Prototype?


When?

Why?

What?

How?

Prototyping (When?)



Concept




Details



Fabrication



Prototyping (Why?)



Feedback



Demonstrate




Feasibility



Milestones!



Prototyping (What?)




Sketches



CAD/
Drawings



Physical




Simulations



Prototype vs Final design

How and why is your prototype different from the final product?

Prototyping (How?)



Prototyping (Budget?)



200 dollars

Per site

For local
expenditure

Operation sheet



DARVIC INDUSTRIES

OPERATION SHEET

PART NAME: Threaded Shaft 1340 Cold Rolled Steel

Part No. 7358-267-10

OPER. NO.	NAME OF OPERATION	MACH. TOOL	CUTTING TOOL	CUTTING SPEED		FEED ipr	DEPTH OF CUT Inches	REMARKS
				ft/min	rpm			
10	Face end of bar	Engine Lathe		120	458	Hand		Use 3-jaw Universal chuck
20	Center Drill End	*	Combination center drill		750	Hand		
30	Cut off to $3\frac{9}{16}$ length	*	Parting tool	120	458	Hand		To prevent chattering, keep overhang of work and tool at a minimum and feed steadily. Use lubricant.
40	Face to length	*	RH facing tool (small radius point)	120	458	Hand	(R) $\frac{1}{8}$ max. (F) .005	Before replacing part in 3-jaw chuck, scribe a line marking the $3\frac{1}{2}$ inch length.
50	Center Drill End	*	Combination center drill		750	Hand		
60	Place between centers, turn .501 diameter, .499 and face shoulder	*	RH turning tool (small radius point)	120 160	(R) 458 (F) 611	(R) .0089 (F) .0029	(R) .081 (3) (F) .007	
70	Remove and replace end for end and turn .877 diameter, .873 diameter	*	RH tools (R) (small radius point) (F) Round nose tool	120 160	(R) 458 (F) 611	(R) .0089 (F) .0029	(R) .057 (F) .005	
80	Produce 45°-chamfer	*	RH round nose tool	120	458	Hand	(R) $\frac{1}{8}$ max. (F) .005	
90	Cut $\frac{7}{8}$ - 14 NF-2 thread	*	Threading tool	60	208		(R) .004 (F) .001	(1) Swivel compound rest to 30 degrees. (2) Set tool with thread gage. (3) When tool touches outside diameter of work set cross slide to zero. (4) Depth of cut for roughing = .004. (5) Engage thread dial indicator on any line. (6) Depth of cut for finishing = .001 Use compound rest.
	Remove burrs and sharp edges	*	Hand file					

Operation sheet



DARVIC INDUSTRIES								
OPERATION SHEET								
PART NAME: Threaded Shaft 1340 Cold Rolled Steel				Part No. 7358-267-10				
OPER. NO.	NAME OF OPERATION	MACH. TOOL	CUTTING TOOL	CUTTING SPEED		FEED ipr	DEPTH OF CUT Inches	REMARKS
				ft/min	rpm			
10	Face end of bar	Engine Lathe		120	458	Hand		Use 3-jaw Universal chuck
20	Center Drill End	*	Combination center drill		750	Hand		
30	Cut off to $3\frac{9}{16}$ length	*	Parting tool	120	458	Hand		To prevent chattering, keep overhang of work and tool at a minimum and feed steadily. Use lubricant.
40	Face to length	*	RH facing tool (small radius point)	120	458	Hand	(R) $\frac{1}{8}$ max. (F) .005	Before replacing part in 3-jaw chuck, scribe a line marking the $3\frac{1}{2}$ inch length.
50	Center Drill End	*	Combination center drill		750	Hand		
60	Place 1 chamfer, 877 99 chamfer, 877 1/8 chamfer, 877	*	RH facing tool (small radius point)	120 180	(R) 458 (F) 611	(R) .008 (F) .0029	(R) .001 (F) .001	
70	Remove and replace end for end and turn 877 diameter	*	RH tools (R) (small radius point) (F) Round nose tool	120 180	(R) 458 (F) 611	(R) .0089 (F) .0029	(R) .057 (F) .005	
80	Produce 45°-chamfer	*	RH round nose tool	120	458	Hand	(R) $\frac{1}{8}$ max. (F) .005	
90	Cut $\frac{7}{8}$ - 14 NF-2 thread	*	Threading tool	60	208		(R) .004 (F) .001	(1) Swivel compound rest to 30 degrees. (2) Set tool with thread gage. (3) When tool touches outside diameter of work set cross slide to zero. (4) Depth of cut for roughing = .004. (5) Engage thread dial indicator on any line. (6) Depth of cut for finishing = .001 Use compound rest.
	Remove burrs and sharp edges	*	Hand file					

NOT REQUIRED IN REPORT

System Integration plans

Subassemblies
& components


Integration
steps

Tools/process
requirements

Time estimate

Testing plans

Steps forward



Locate manufacturing facilities globally



In your final report

Identify manufacturing processes


Identify manufacturing location(s)

Provide rationale


State advantages

State areas of concern (if any)


Steps forward




Inputs to MRP




Material requirements planning (MRP)



MRP Outputs




Material Requirements Planning




Distribution requirements planning

Some project groups also have to consider this



Steps forward



Question time

