

Manual NC

October, 26, 2009

Professor Sung-Hoon Ahn
TA: Hyung-Jung Kim

School of Mechanical and Aerospace Engineering
Seoul National University



Contents

1. Identifying letters of commands
2. Basic preparatory commands
3. Basic Miscellaneous commands
4. Simple Example
5. Exercise problems

Words

1. N code

- Line number
ex. N001 O1234 → first line of the program and O1234 is the program number (usually the program # is located)

2. G code

- Prepare the controller for a given operation
ex. G00 X10.0 → move to positive X-direction by 10.0 mm
G00: point to point, positioning (use with combination point-to-point/contouring systems for indicating positioning operation)

3. Dimension words (X, Y, Z, A, and B words)

- Location and axis orientation of a cutter A, B are for machine with more than 3 axis
ex. Y + 500 → if the unit BLU (Basic Length Unit) is 0.0254 mm, it means 12.7 mm moving from Y location

Words (cont.)

4. F code (feed command)

- Cutter feed rate (mm/min, millimeters per minute)
ex. F2.0 → move 2 mm per minute

5. S code

- Specify spindle speed
ex. S5000 → Spindle speed is specified by 5000 rpm

6. T code

- Tool selection command
- Used when the machine is equipped with a tool turret
ex. T1 → call the tool # 1 in the tool turret



Words (cont.)


7. M code

- Miscellaneous commands
- Coolant supply, spindle on/off, etc.
- ex. M06 → tool change, executes the change of a tool (tools manually or automatically, not to include tool selection)

Words (cont.)

Word address format

- Used by most CNC controllers
- $N_ G_ X_ Y_ Z_ I_ J_ K_ F_ S_ T_ M_$



- ex. N0010 G01 X07500 Y06250 S612
- Omitted words are assumed to zero or to be the same as the value previously defined


```

N001 G92 G91 X0.0
Y0.0 Z20 ;
N002 G00 Z-8.0 ;
N003 G01 Z-20.0 F80 ;
N004 Y5.0 ;
N005 X10.0 ;
N006 G03 X12.5 Y12.5
R12.5 ;
N007 G02 X20 Y20
R30 ;
  
```

Basic preparatory commands

G Code

- G90 : Absolute dimension programming
- G91 : Incremental dimension programming
- G92 : Coordinate origin position setting
- G00 : Point to point, positioning
- G01 : Linear interpolation




Absolute dimension
G90 G01 X412. Y436. F250;

Incremental dimension
G91 G01 X112. Y36. F250;

Basic preparatory commands (cont.)

G Code

- G17 : XY Plane selection
- G18 : YZ Plane selection
- G19 : ZX Plane selection
- G02 : Circular interpolation arc CW
- G03 : Circular interpolation arc CCW



Example

```
G17
G02 X-28.28 Y0.0 I14.14 J5.0
```


```
G18
G02 Y0.0 Z5.0 J5.0 K5.0
```

```
G19
G02 Z5.0 X10.0 K5.0 I5.0
```

Basic preparatory commands (cont.)

▪ G Code


- G40 : Cutter compensation for tool diameter – cancel
- G41 : Cutter compensation for tool diameter – left
- G42 : Cutter compensation for tool diameter – right



Basic preparatory commands (cont.)

▪ G Code

- G43 : Cutter compensation for tool length – "+"
- G44 : Cutter compensation for tool length – "-"
- G49 : Cutter compensation for tool length – Cancel



Basic miscellaneous commands

▪ M Code


- M02 : End of program
- M03 : Spindle CW
- M04 : Spindle CCW
- M05 : Spindle off
- M30 : End of tape
(Similar to M02, except that it is ready for the next work piece)

Manual NC Viewer

▪ Gcode2000

- Download from the web class,
and extract it on your computer

Simple Example



Tool Diameter $\phi 20$


Tool position : X0.0 Y0.0 Z3.0
 Feed 120
 Depth : 5
 ① and ⑭ are not for machining

Simple Example (cont.)

- **Initialization**
 Absolute or Incremental dimension
 Set feed rate and start spindle
- **Incremental dimension programming**
- **① Path**
 G92 G91 X0.0 Y0.0 Z3.0 ;
 G00 X70 Y30 ;
 M03;
 G01 Z-8.0 F120;


Simple Example (cont.)

- **②~⑥ Path**
 G01 X70.0;
 G01 Y50.0;
 G01 X20.0;
 G01 Y-50.0;
 G01 X40.0;
- **⑦ Path**
 G03 X40.0 Y40.0 I0.0 J40.0;
 (or G03 X40.0 Y40.0 R40.0;)
- **⑧~⑨ Path**
 G01 Y40.0;
 G01 X-10.0;



Simple Example (cont.)


- **⑩ Path**
 G02 X-20.0 Y20.0 I0.0 J20.0;
 (or G02 X-20.0 Y20.0 R20.0;)
- **⑪~⑬ Path**
 G01 Y10.0;
 G01 X-140.0;
 G01 Y-110.0;
- **⑭ Path**
 G01 Z8.0;
 M05;
 G00 X-70.0 Y-30.0
 M30



Simple Example (cont.)

- Absolute dimension programming


```
G92 G90 X0.0 Y0.0 Z3.0 ;
G00 X70 Y30 ;
M03;
G01 Z-5.0 F120;
G01 X140.0;
G01 Y80.0;
G01 X160.0;
G01 Y30.0;
G01 X200.0;
G03 X240.0 Y70.0 I200.0 J70.0;
G01 Y110.0;
G01 X230.0;
```




Simple Example (cont.)

- Absolute dimension programming

```
G02 X210.0 Y130.0 I230.0 J130.0;
G01 Y140.0;
G01 X70.0;
G01 Y30.0;
G01 Z3.0;
M05;
G00 X0.0 Y0.0
M30
```



Exercise problem 1




Tool position : X0.0 Y0.0 Z3.0
Feed 250
Depth : 3

Exercise 1 answer (I)

- Incremental dimension programming


```
G92 G91 X0.0 Y0.0 Z3.0 ;
G00 X-5 Y10 ;
M03;
G01 Z-6.0 F250;
G01 Y10.0;
G03 X-20.0 Y20.0 I-20.0 J0.0;
G02 X0.0 Y50.0 I0.0 J25.0;
G01 X75.0;
G02 X20.0 Y-20.0 I0.0 J-20.0;
```



Exercise 1 answer (II)


Incremental dimension programming

```
G02 X-15.0 Y-15.0 I-15.0 J0.0 ;
G03 X-5.0 Y-5.0 I0.0 J-5.0 ;
G01 Y-3.0903;
G01 X-20.0 Y-31.9097
G01 X-35.0 ;
G01 Z6.0 ;
M05 ;
G00 X5 Y-10 ;
M30 ;
```



Exercise problem 2

Pocket machining




Tool position : X0.0 Y0.0 Z3.0
 Feed 250
 Depth : 3
 Tool Diameter : 5

Exercise 2 answer (I)

Incremental dimension programming


```
G92 G91 X0.0 Y0.0 Z3.0 ;
G00 X2.5 Y12.5 ;
M03;
G01 Z-6.0 F250;
G01 Y15.0;
G01 X20.0;
G01 Y2.5;
G02 X15.0 Y0.0 I7.5 J0.0;
G01 Y-2.5;
G01 X20.0;
G01 Y-15.0;
G01 X-55.0;
```



Exercise 2 answer (II)

Incremental dimension programming

```
G01 X2.5 Y2.5;
G01 Y10.0;
G01 X20.0;
G01 Y5.0;
G02 X10.0 Y0.0 I5.0 J0.0;
G01 Y-5.0;
G01 X20.0;
G01 Y-10.0;
G01 X-50.0;
```



Exercise 2 answer (III)



- **Incremental dimension programming**

```
G01 X2.5 Y2.5;  
G01 Y5.0;  
G01 X20.0;  
G01 Y7.5;  
G02 X5.0 Y0.0 I2.5 J0.0;  
G01 Y-7.5;  
G01 X20.0;  
G01 Y-5.0;  
G01 X-45.0;
```



Exercise 2 answer (VI)



- **Incremental dimension programming**

```
G01 X2.5 Y2.5;  
G01 X20.0;  
G01 Y10.0;  
G01 Y-10.0;  
G01 X20.0;  
G01 Z6.0;  
M05 ;  
G00 X-50.0 Y-20.0 ;  
M30 ;
```

