446.305A MANUFACTURING PROCESSES

### Chapter 4. Surfaces, Tribology, Dimensions, Inspection & Quality

#### **Sung-Hoon Ahn**

School of Mechanical and Aerospace Engineering Seoul National University

### Introduction



#### Surface properties affect

- Friction and wear
- Lubrication
- Painting, coating, welding, soldering, adhesive bonding, corrosion resistance
- Crack initiation
- Thermal and electrical conductivity

#### Tribology

- Friction
- Wear
- Lubrication

### **Surface structure**



#### Oxide layer (hard, brittle, abrasive)

- Iron: FeO, Fe3O4, Fe2O3
- Aluminum: Al<sub>2</sub>O<sub>3</sub>
- Copper: Cu<sub>2</sub>O, CuO
- Stainless steel: CrO
- Beilby layer: melting & surface flow-> rapid quenching
- Work-hardened layer: residual stress



S. Kalpakjian, "Manufacturing Processes for Engineering Materials",  $3^{rd}/4^{th}$  ed. Addison Wesley

#### **Surface texture**

■ Flaw (흠)/ defect (결함), lay (가공무늬), roughness (거칠기), waviness (파상도)





Ref.

S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley

#### **Surface roughness**

profiles produced by (c) lapping, (d) finish grinding, (e) rough grinding, and (f) turning processes. Note the difference between the vertical and horizontal scales. *Source*: from D. B.

Dallas (ed.), Tool and Manufacturing Engineers Handbook, 3d ed.





(f) Turning



S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley

# R<sub>a</sub> and R<sub>q</sub>



#### Arithmetic mean value

- arithmetic ave. (AA)
- center-line ave. (CLA)
- Root-mean-square ave. (RMS)

$$R_{a} = \frac{y_{a} + y_{b} + y_{c} + y_{d} \cdots}{n} = \frac{1}{n} \sum_{i=1}^{n} y_{i} = \frac{1}{l} \int_{0}^{l} |y| dx$$
$$R_{q} = \sqrt{\frac{y_{a}^{2} + y_{b}^{2} + y_{c}^{2} + y_{d}^{2} + \cdots}{n}} = \sqrt{\frac{1}{n} \sum_{i=1}^{n} y_{i}^{2}} = \left[\frac{1}{l} \int_{0}^{l} y^{2} dx\right]^{\frac{1}{2}}$$

- Rough surface:
  - Lower precision, short fatigue life, higher electrical & thermal contact resistance, lower corrosion resistance, better painting & coating, lower cost



# Atomic Force Microscope (AFM) Tip





**Before PZT process** 

After PZT process

#### **Friction**



- Adhesion theory of friction (응착이론)
  - Intimate contact of asperities creates an adhesive bond



ļ

Ļ

**FIGURE 4.5** (a) Schematic illustration of the interface of two contacting surfaces, showing the real areas of contact. (b) Sketch illustrating the proportion of the apparent area to the real area of contact. The ratio of the areas can be as high as four to five orders of magnitude.

■ Friction coefficient (마찰계수)

FIGURE 4.6 Schematic illustration of the relation between friction force F and normal force N. Note that as the real area of contact approaches the apparent area, the friction force reaches a maximum and stabilizes. Most machine components operate in the first region. The second and third regions are encountered in metalworking operations, because of the high contact pressures involved between sliding surfaces, i.e., die and workpiece.



$$u = \frac{F}{N} = \frac{\tau A_r}{\sigma A_r} = \frac{\tau}{\sigma} \qquad friction(shear) \ factor, \ m = \frac{\tau_i}{k}$$

$$k(shear \ yield \ stress) = Y/2$$

$$\mu = \frac{\tau}{hardness} = \frac{\frac{\tau}{\sqrt{3}}}{\frac{1}{3Y}} \approx 0.2$$

$$\mu = \frac{\tau}{\sigma} = \frac{\frac{\tau}{\sqrt{3}}}{\frac{1}{3Y}} \approx 0.577$$

Ref. S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley



#### **Measuring Friction**

#### Ring compression test



**FIGURE 4.8** Charts to determine friction in ring compression tests: (a) coefficient of friction,  $\mu_5$  (b) friction factor, *m*. Friction is determined from these charts from the percent reduction in height and by measuring the percent change in the internal diameter of the specimen after compression.

Ref. S Kalpakijan "M

S. Kalpakjian, "Manufacturing Processes for Engineering Materials",  $3^{rd}/4^{th}$  ed. Addison Wesley

# **Wear (1)**



 Progressive loss of material from a surface



■ Adhesive wear (응착마멸)



Archard wear law

$$V = k \frac{LW}{3p}$$

Ref. S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley

# Wear (2)



#### Abrasive wear



**FIGURE 4.11** Schematic illustration of abrasive wear in sliding. Longitudinal scratches on a surface usually indicate abrasive wear.

- Corrosive wear
- Fatigue wear

FIGURE 4.12 Types of wear observed in a single die used for hot forging. Source: Top die T. A. Dean. 153421 2 (5) 15341 (5) Bottom die Ejector 1. Erosion 2. Pitting (lubricated dies only) 3. Thermal fatigue 4. Mechanical fatigue 5. Plastic deformation Ę.

Ref. S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley

### Lubrication



4 regimes of lubrication





#### Ref.

S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley

### **Surface Treatment (1)**

- Shot peening, water-jet peening, laser peening
- Roller burnishing (surface rolling)
- Cladding (clad bonding)
- Mechanical plating
- Thermal spraying
- Surface texturing

FIGURE 4.15 Examples of roller burnishing of (a) a conical surface and (b) a flat surface and the burnishing tools used. *Source*: Cogsdill Tool Products.





S. Kalpakjian, "Manufacturing Processes for Engineering Materials",  $3^{\rm rd}/4^{\rm th}\,\text{ed}.$  Addison Wesley

# **Surface Treatment (2)**

- Vapor deposition (CVD/PVD/ Ion implantation)
- Electroplating/ electroless plating
- Electroforming
- Anodizing
- Diamond coating



Ref. S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley

# Cold spray (1)

- High deposition rate at low temperature
- Accelerated powder particles are sprayed onto substrate.
- Fabrication type : constructive process
- Typical substrate materials : metal









Schematic diagram

## Cold spray (2)



Repair of damaged mold



#### Nano particle deposition system (NPDS)

- High deposition rate at room temperature
- Aerosol with particles is accelerated by a gas flow and sprayed onto substrate.
- Fabrication type : constructive process
- Typical substrate materials : metal, ceramic







Schematic diagram

#### **Fabrication envelop**



#### Mn-Zn ferrite coating on Al 6061 with niddles



TiO<sub>2</sub> coating on Stainless steel

#### Measurement



- Length: dial indicator, LVDT
- Straightness : autocollimators
- Flatness: interferometry
- Roundness: total indicator reading (TIR), full indicator movement
- Profile
- Coordinate measuring machines (CMM) and layout machines
- Gages
- Microscopes



### **Precision & Accuracy**

- Accuracy(정확도)
  - degree of conformity of a measure to a standard or a true value(closeness to the true value, δ<sub>m</sub>)
- Precision(정밀도)
  - the degree of refinement with which an operation is performed or a measurement stated(size of standard deviation, σ)



#### **Precision & Accuracy – example**



- Precise
- Not accurate



- Accurate
- Not precise



- Accurate
- Precise

#### **Dimensional Tolerance**



**FIGURE 4.19** (a) Basic size, deviation, and tolerance on a shaft, according to the ISO system. (b)–(d) Various methods of assigning tolerances on a shaft. *Source:* L. E. Doyle.

S. Kalpakjian, "Manufacturing Processes for Engineering Materials", 3<sup>rd</sup>/4<sup>th</sup> ed. Addison Wesley

### **Quality Assurance**



Normal (Gaussian) Distribution

$$\overline{x} = \frac{x_1 + x_2 + x_3 + \dots + x_n}{n}$$
Range,  $R = x_{\max} - x_{\min}$ 

$$\sigma = \sqrt{\frac{(x_1 - \overline{x})^2 + (x_2 - \overline{x})^2 + (x_3 - \overline{x})^2 + \dots + (x_n - \overline{x})^2}{n - 1}}$$

#### Control Chart

Upper control lmit( $UCL_{\overline{x}}$ ) =  $\overline{x} + 3\sigma = \overline{\overline{x}} + A_2\overline{R}$ Lower control lmit( $LCL_{\overline{x}}$ ) =  $\overline{x} - 3\sigma = \overline{\overline{x}} - A_2\overline{R}$ 

- Six sigma (3~4 ppm)
- ISO 9000 (quality management & quality assurance)
- ISO 14000 (environmental management)

Ref.

S. Kalpakjian, "Manufacturing Processes for Engineering Materials",  $3^{\rm rd}/4^{\rm th}\,\text{ed}.$  Addison Wesley

### **Control Chart**



#### **Process Capability Indices**

Process Capability Index, Cp

$$C_p = \frac{USL - LSL}{6\sigma_x}$$

- Minimum acceptable value for C<sub>p</sub> is 1
- Desirable value : 1 ~ 2

#### Process Capability Index, Cpk

$$Z_{USL} = \frac{USL - \mu_x}{\sigma_x} \qquad \qquad Z_{LSL} = \frac{LSL - \mu_x}{\sigma_x}$$

 $\mu_x$ : process mean  $Z_{\min} = \min |Z_{USL}, or (-Z_{LSL})|$  $C_{pk} = \frac{Z_{\min}}{3} \ge 1.0$ 



#### **Process Capability Indices - example**



= -3