

2. BOILING WATER REACTOR AND **FUKUSHIMA DAIICHI NUCLEAR DISASTER**

References

1. The Development of and Lessons from the Fukushima Daiichi Nuclear Accident
2. The Fukushima daiichi accident
Technical volume 1: description and context of the accident

The Development of
and Lessons from
the Fukushima Daiichi
Nuclear Accident



Fukushima Daiichi Nuclear Power Station, prior to the accident
(from left to right: Units 1, 2, 3, and 4, photographed November 2000)

The Fukushima Daiichi Accident

 **Technical Volume 1/5**
Description and Context of the Accident

 **IAEA**
International Atomic Energy Agency



Fukushima Daiichi Nuclear Disaster

❖ Overall




Fukushima Daiichi Nuclear Disaster

❖ Safety Philosophy

- Nuclear reactors are designed to maintain safety based on a philosophy of
 - Shutting down, Cooling down, Confining inside


0. Protect



Design mindful of the height of tsunami and strength of earthquakes

Elements on the site of a power station are designed with provisions for the onslaught of conceivable earthquakes and tsunami.

1. Shutting down



Emergency shutting down through insertion of control rods


Control rods are swiftly inserted in emergencies such as major earthquakes and the reactor undergoes an emergency shutting down.

Fukushima Daiichi Nuclear Disaster

❖ Safety Philosophy

- Nuclear reactors are designed to maintain safety based on a philosophy of
 - Shutting down, Cooling down, Confining inside


2. Cooling down



Cooling of the pressure vessel through injection and circulation of water

Equipment for sending a large amounts of water into the reactor is installed so that the fuel does not rise to high temperatures and the reactor core is not heating while empty.

3. Confining inside



Radioactive materials are confined inside with pressure vessels, primary containment vessels, and the like

Protective walls are installed to confine inside radioactive materials so that they do not get outside even in an accident.

Fukushima Daiichi Nuclear Disaster

❖ Safety Philosophy



- If cooling fails



If cooling fails...

Water level in the pressure vessel falls, leading to core damage.

If cooling cannot be performed, it becomes difficult to continue keeping material confined inside. When confining inside fails, it leads to the release of hydrogen and radioactive materials to the outside.



Fukushima Daiichi Nuclear Disaster

❖ Cooling system of Fukushima Daiichi Units 2 and 3

- The cause of the accident at Fukushima was the failure to “Cooling Down”.
- What does it mean to "cool" a nuclear reactor?
 - The objective of "cooling" a reactor is
 - To achieve a state wherein the reactor is stabilized at "cold shutdown"
 - Cold shutdown
 - Condition in which the temperature of the water within the reactor is below 100°C
- Decay heat removal capability should be provided with
 - Coolant injection
 - Depressurization
 - Heat removal

Fukushima Daiichi Nuclear Disaster


❖ Cooling system of Fukushima Daiichi Units 2 and 3

● HPCI/RCIC

- Passive cooling system
- Available in the event of SBO

● ADS

- Passive system
- Available in the event of SBO



Fukushima Daiichi Nuclear Disaster

❖ Cooling system of Fukushima Daiichi Units 2 and 3

● LPCI/LPCS


- Active system
- Not available in the event of SBO
- Fire protection system was prepared.

● RHRS

- Active system
- Not available in the event of SBO

● PCV Vent

- AC power is required.



❖ Protection measures

- Shut-down system
- Cooling system
 - Coolant injection
- Containment system

❖ Normal shut-down

- High pressure cooling:
- Low pressure cooling:

❖ Emergency shut-down


- High pressure cooling:
- Depressurization:
- Low pressure cooling:

Fukushima Daiichi Nuclear Disaster

❖ Operation of cooling system in Fukushima Daiini Power Station

High-pressure coolant injection


Depressurization



Water level is maintained by the HPCI system (or RCIC system), and pressure in the pressure vessel is lowered using the safety relief valve.

Low-pressure coolant injection

Depressurization




Water level is maintained through low-pressure coolant injection (make-up water condensate system), and pressure in the primary containment vessel is raised by transferring steam from the pressure vessel to the primary containment vessel.


Fukushima Daiichi Nuclear Disaster

❖ Operation of cooling system in Fukushima Daiichi Power Station

Heat removal




By starting heat removal, the flow of steam from the pressure vessel is halted while the primary containment vessel cools and its pressure gradually falls.



Fukushima Daiichi Nuclear Disaster

❖ Operation of cooling system in Fukushima Daiichi Power Station



Fukushima Daiichi Nuclear Disaster

❖ Development of the accident

- Loss of cooling function ⇐ loss of power sources
 - Water in RPV ran out.
 - Fuel temperature rose.
 - Hydrogen was generated in large quantities.
 - Fuel melted.
 - RPVs were damaged.
 - PCVs were damaged.
 - Both hydrogen and radioactive materials were released into the reactor buildings.

Summary of developments at each unit

3/15 06:14 Unit 4 hydrogen explosion

Unit

3/11

3/12

3/13

3/14

3/15

3/11 15:35
Tsunami hits

3/12 15:36
Unit 1 hydrogen explosion

3/14 11:01
Unit 3 hydrogen explosion

Unit 1

1 2 3 4 5

Unit 2

1

Coolant injection continued

2 3 4 5

Unit 3

Coolant injection continued

1 2 3 4 5



The timing differed at Fukushima Daiichi Units 1, 2, and 3, but each went through the same process resulting in the releases of hydrogen and radioactive materials.

- 1 Total power failure
- 2 Loss of "cooling down" functions
- 3 Water level drops

- 4 Core damage and hydrogen generation
- 5 Hydrogen and radioactive material leaks


Fukushima Daiichi Nuclear Disaster

❖ Development of the accident



Fukushima Daiichi Nuclear Disaster

❖ Development of the accident




Tsunami waves




Fukushima Daiichi Nuclear Disaster

❖ Development of the accident

- Decay Heat produces steam in Reactor pressure Vessel
- Pressure increase




Core degradation stopped by sea water injection.



Fukushima Daiichi Nuclear Disaster


❖ Development of the accident



Fukushima Daiichi Nuclear Disaster


❖ Earthquake and Tsunami

- No damage from the earthquake to key safety features
 - Emergency trips were made.
 - Emergency diesel generators started up.
- Tsunami arrived about 50 minutes after the earthquake.
- Coolant injection and heat removal were lost.
- A variety of damage was inflicted
 - Spread of debris by the tsunami that prevented people from moving around site.



- 1 Air supply louver for emergency diesel generator
- 2 Turbine building entrance
- 3 Component hatch


Height of Fukushima Daiichi Nuclear Power Station grounds and tsunami (illustration)



Fukushima Daiichi Nuclear Disaster

❖ Earthquake and Tsunami

The wave flooded and damaged the unhoused seawater pumps and motors of all six units at the seawater intake locations on the shoreline, resulting in loss of ultimate heat sink events for all units. This meant that essential plant systems and components, including the water cooled EDGs¹⁴, could not be cooled to ensure their continuous operation.




Each unit had a pair of EDGs, and Unit 6 had an additional generator. Of those 13 EDGs, Units 2, 4 and 6 each had one that was air cooled. Since they were air cooled, operability of these generators was not directly affected by the loss of cooling water caused by the damage to the seawater pumps.


Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-1

14:46 Earthquake occurred



15:35 Tsunami hits



Isolation condenser became unusable due to the tsunami

The isolation condenser can perform cooling just by opening and closing a valve. The valve on the isolation condenser was opened and closed to slowly cool the reactor core after the earthquake. However, this valve was closed when all power was lost due to the tsunami. It could not be reopened for that reason, and the isolation condenser lost its cooling function.

3/11

Cold shutdown process in normal conditions

Reactor automatically trip (scram)

Electrical power supplied by transmission lines

Cooling by the condenser

Cooling (heat removal) by the residual heat removal system

Cold shutdown

Cold shutdown process in an emergency

Power provided by generator operating with diesel fuel (emergency diesel generator)

Cooling with water under high pressure (high-pressure coolant injection)


Lower pressure of pressure vessel (depressurization)

Cooling continuously with water (low-pressure coolant injection)


Cooling (heat removal) by the residual heat removal system

Cold shutdown

Turbine building, Control building




Turbine building, Control building



Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-1


Hydrogen leaks into building



15:36 Hydrogen explosion in the Unit 1 reactor building



Water vapor reacted chemically with zirconium on the exterior of the fuel rods and hydrogen was generated in a large massive amounts



3/12

Around 4:00 a.m.

Fuel exposure and damage (heating white empty conditions)

Pressure vessel damage

Container vessel damage

Hydrogen leaks into building



Fire engines cool by injecting coolant



Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-1

All the inside containment isolation condenser valves (AC operated) would keep their position when the AC power was lost, but they would close, by design, if the control power (i.e. DC power) was lost to the protection system — for the line break situation — that would have sent 'close signal' signals to those valves. The position of AC-powered isolation valves has not yet been confirmed by post accident investigations.



Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-1

The shift team opened the outboard isolation valves from the MCR (remote-manually) at 18:18, taking the chance that the other isolation valves were in an open position. **After opening the outer isolation valves of Train A, a small amount of steam was observed above the RB of Unit 1, suggesting the onset of IC operation.** However, these indirect signs of an operating IC disappeared after a short time. As there were questions concerning the soundness of the IC system, and as it was not operating as expected, the outboard isolation valve in the condensate leg of the IC was remote-manually closed again at 18:25, which was not reported to the ERC.

| | | | | |
|------------------|-------------|--|--|-------------|
| 2011-03-11 18:18 | 03 h 32 min | Indications show both outboard IC valves closed. | Operators found that the valve indicator lamps were lit sometime before 18:18. Not only MO-3A, which was controlled by operators for IC activation/deactivation and was left closed before the second wave of the tsunami, but also the IC supply piping containment isolation valve (MO-2A), which was normally open was closed. Thus, operators inferred that an IC isolation signal was generated during the loss of control (DC) power, possibly by the IC pipe rupture detection circuit. It was corroborated that they were closed at the time of DC failure; thus, there was no shutdown heat removal since then. | 02 h 41 min |
| 2011-03-11 18:18 | 03 h 32 min | Operator started IC by opening the motor operated IC valves MO-3A and MO-2A. | Outboard (outside containment) valves of Train A, assuming that the inboard valves (which cannot be controlled without power) were open since they would fail as-is in the case of loss of AC power. They failed open since they were open at the time of the SBO. | 02 h 41 min |
| 2011-03-11 18:18 | 03 h 32 min | IC observed to be operating. | Steam was observed from the IC exhaust area for a short duration. It was reported to the station ERC that IC is operating. | 02 h 41 min |
| 2011-03-11 18:25 | 03 h 39 min | IC operation cannot be confirmed. | Steam that was observed from the IC exhaust area ceased. There was a doubt regarding the integrity of the IC system. Possible causes were: inboard valves closed, IC tank inventory depleted, line break, etc. | 02 h 48 min |
| 2011-03-11 18:25 | 03 h 39 min | Operator closed the motor operated IC valves MO-3A, securing IC. | — | 02 h 48 min |

Fukushima Daiichi Nuclear Disaster


❖ Severe accident at Unit-1

| | | | | |
|------------------|-------------|---|---|-------------|
| 2011-03-11 20:07 | 05 h 21 min | High reactor pressure. | Reading of the gauge in the reactor building. This pressure reading further suggested that the IC was not working. | 04 h 30 min |
| 2011-03-11 20:30 | 05 h 44 min | Established alternative water injection line from the fire protection system to the core spray began operation, sending crew to the reactor building. | By manual alignment of injection line in the reactor building. No unusual exposure is observed from APDs. | 04 h 53 min |
| 2011-03-11 20:40 | 05 h 54 min | DDFP started. | DDFP operation switch was moved from the shutdown position in the MCR, having been manually held since placing the DDFP in standby earlier to prevent unintended start. | 05 h 03 min |
| 2011-03-11 20:40 | 05 h 54 min | DDFP failed to start. | Operators in the reactor building kept resetting the fault trip. | 05 h 03 min |
| 2011-03-11 20:50 | 06 h 04 min | DDFP started continuous operation. | DDFP stopped tripping on fault. | 05 h 13 min |
| 2011-03-11 20:50 | 06 h 04 min | Water injection not achieved. | The pump head of the DDFP is 7.9 bar. | 05 h 13 min |
| 2011-03-11 22:00 | 07 h 14 min | Increased reactor water level. | An earlier reading was TAF + 450 mm. | 06 h 23 min |
| 2011-03-11 22:10 | 07 h 24 min | Reactor water level above TAF reported to government officials. | TAF + 450 mm. | 06 h 33 min |
| 2011-03-11 23:00 | 08 h 14 min | High dose rate reading in front of the north door of the reactor building on the 1st floor of the TB. | The dose rate inside the reactor building was extrapolated to be ~300 mSv/h. | 07 h 23 min |
| 2011-03-11 23:00 | 08 h 14 min | High dose rate reading in front of the south door of the reactor building on the 1st floor of the TB. | | 07 h 23 min |
| 2011-03-11 23:05 | 08 h 19 min | Entry to the reactor building restricted. | Due to the rising radiation levels, ordered by the Site Superintendent. Radiation zone (restricted entry) signs were posted at 23:33 and 23:50 on the north and south air lock doors, respectively. | 07 h 28 min |
| | | | | |
| 2011-03-11 23:50 | 09 h 04 min | Temporary generator powered the dry well pressure instrument. | Small generator used for temporary MCR lighting was connected to DW pressure instrumentation. | 08 h 13 min |
| 2011-03-11 23:50 | 09 h 04 min | Dry well pressure high. 6 bar | The first measurement since loss of DC power. | 08 h 13 min |

Fukushima Daiichi Nuclear Disaster


❖ Severe accident at Unit-1

A. Normal operation




Measured water level matches with actual water level

B. After decompression boiling



Measured water level appears higher than actual water level due to drop of reference water level

C. Decompression boiling + water level is below lower piping



Measured water level always appear higher than actual water level without being affected by actual changes in water level

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-1

| | | | | | |
|------------------|-------------|--|--|--|-------------|
| 2011-03-12 00:06 | 09 h 20 min | The Site Superintendent directed preparations to vent the PCV. | | In the MCR, operators assembled piping and instrumentation drawings, accident management procedures, valve drawings, and a white board. The operators began to develop a procedure for venting, including how to manually operate the valves, and the associated sequence. Operators collected the equipment needed to perform the evolution, including fire-fighting turnout gear, SCBAs, dosimeters, survey meters, and flashlights. | 08 h 29 min |
| 2011-03-12 00:30 | 09 h 44 min | Evacuation of the 3 km zone completed. | PCV pressure (DW) > design pressure (5.28 bar) | Government confirmed the completion of evacuation. Evacuation for residents within a 3 km radius of Futaba and Okuma Towns was confirmed as being completed, reconfirmed at 01:45. Completion of evacuation to start the venting was agreed with the Fukushima Prefecture authorities. | 08 h 53 min |
| 2011-03-12 02:30 | 11 h 44 min | Reactor water level reading taken. | TAF+ Ch. A 1300 mm, Ch. B 530 mm | The reliability of these readings are questionable. | 10 h 53 min |
| 2011-03-12 02:30 | 11 h 44 min | Maximum (recorded) containment (DW) pressure. | 8.4 bar | Subsequently, the pressure decreased. | 10 h 53 min |
| 2011-03-12 02:45 | 11 h 59 min | DW pressure decreased. | 8 bar | Pressure stabilized between 7 and 8 bar (700–800 kPa) afterwards. | 11 h 08 min |
| 2011-03-12 04:00 | 13 h 14 min | Water injection into the reactor by one fire engine. | | One fire truck's inventory was pumped through the FP line. | 12 h 23 min |
| 2011-03-12 06:50 | 16 h 04 min | METI issued the order for containment venting. | | Venting of both Units 1 and 2 containments was issued in accordance with the Act on Special Measures Concerning Nuclear Emergency Preparedness. | 15 h 13 min |
| 2011-03-12 07:11 | 16 h 25 min | The Prime Minister arrived at the site. | | — | 15 h 34 min |
| 2011-03-12 08:04 | 17 h 18 min | The Prime Minister left the site. | | — | 16 h 27 min |

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-1

| | | | | |
|------------------|-------------|---|--|-------------|
| 2011-03-12 09:04 | 18 h 18 min | Start of venting. | — | 17 h 27 min |
| 2011-03-12 09:04 | 18 h 18 min | Team 1 (of 3) was dispatched to manually open containment vent valves (motor and air operated). | The control room operators formed three teams to perform the venting, with two operators on each team (one to perform actions and the other to assist by holding flashlights and monitoring dose rates and for other safety concerns, such as ongoing aftershocks). Because there was no means of communicating with the field teams, the decision was made to dispatch one team at a time, with the next team leaving only after the preceding team returned. | 17 h 27 min |
| 2011-03-12 09:05 | 18 h 19 min | Commencement of venting conveyed to the public through the press. | — | 17 h 28 min |

Effort for suppression chamber venting



| | | | | |
|------------------|----------------|---|--|-------------|
| 2011-03-12 09:24 | 18 h 38 min | Team 2 (of 3) dispatched to manually open the suppression chamber vent valve for containment venting. | The control room operators formed three teams to perform the venting, with two operators on each team. | 17 h 47 min |
| 2011-03-12 09:32 | 18 h 46 min | Attempt to manually open the air operated suppression chamber vent by-pass valve failed. | The second team of operators was unsuccessful in the attempt to manually open the suppression chamber air operated vent valve. The operators entered the torus room but had to turn back because they expected they would exceed the 100 mSv dose limit. | 17 h 55 min |
| 2011-03-12 10:17 | 19 h 31 min | The first attempt to remotely open smaller (bypass) air operated suppression chamber vent valve failed. | Operators attempted to open the suppression chamber AOV remotely from the MCR utilizing residual air pressure in the instrumentation air system and temporary DC power supplied by batteries. | 18 h 40 min |
| 2011-03-12 10:23 | 19 h 37 min | The second attempt to remotely open air operated suppression chamber vent bypass valve failed. | | 18 h 46 min |
| 2011-03-12 10:24 | 19 h 38 min | The third attempt to remotely open air operated suppression chamber vent bypass valve failed. | | 18 h 47 min |
| 2011-03-12 14:30 | 23 h 44 min | The large (isolation) suppression chamber venting valve (AO) was opened. | Inferred from the following PCV pressure drop (sometime between 14:00 and 14:30). | 22 h 53 min |
| 2011-03-12 14:30 | 23 h 44 min | Venting commenced. | The venting and release of radioactive material were confirmed through an indicated decrease in containment pressure. | 22 h 53 min |
| 2011-03-12 14:50 | 01 d 00 h 04 m | Containment pressure decreased. | Due to successful venting. | 23 h 13 min |

Explosion in Unit 1

| | | | | |
|------------------|----------------|----------------------|--|-------------|
| 2011-03-12 15:36 | 01 d 00 h 50 m | Explosion in Unit 1. | The explosion damaged seawater injection and 480 V grid setup. | 23 h 59 min |
|------------------|----------------|----------------------|--|-------------|

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-1



Fukushima Daiichi Nuclear Disaster


❖ Severe accident at Unit-1

After explosion in Unit 1

| | | | |
|------------------|----------------|---|-----------|
| 2011-03-12 15:36 | 01 d 00 h 50 m | Explosion in Unit 1. | |
| 2011-03-12 15:36 | 01 d 00 h 50 m | 480 V low voltage grid connection damaged from explosion. | |
| 2011-03-12 15:36 | 01 d 00 h 50 m | Seawater injection lineup damaged from explosion. | |
| 2011-03-12 15:36 | 01 d 00 h 50 m | MCR lighting lost. | |
| 2011-03-12 15:36 | 01 d 00 h 50 m | PCV pressure measurement lost | |
| | | | |
| 2011-03-13 13:37 | 01 d 22 h 51 m | PCV pressure measurement re-established. | — |
| 2011-03-13 13:37 | 01 d 22 h 51 m | SC pressure reading. | 0.590 MPa |
| 2011-03-13 13:37 | 01 d 22 h 51 m | DW pressure reading. | 0.595 MPa |


| | | |
|------------------|----------------|--|
| 2011-03-12 19:04 | 01 d 04 h 18 m | Damaged hoses for water injection repaired. |
| 2011-03-12 19:04 | 01 d 04 h 18 m | Seawater injection into reactor started upon start of the fire engine. |
| 2011-03-12 20:45 | 01 d 05 h 59 m | Boric acid added to the seawater injection. |

Summary of developments at each unit



Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-2




Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-2

A.M. Release of radioactive materials
outside reactor building

19:54 Start coolant injection



Depressurization
Succeeded!

Coolant injection
was delayed.

3/15


Lower pressure of
pressure vessel
(depressurization)

Fuel exposure and
damage (heating while
empty conditions)

Pressure vessel damage





Container vessel damage

Failure in suppression pool?



Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-2



Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-2

| | | |
|------------------|-------------|--|
| 2011-03-11 15:41 | 55:00 (min) | SBO |
| 2011-03-11 15:41 | 55:00 (min) | DC power panel flooded and failed. |
| 2011-03-11 15:41 | 55:00 (min) | Loss of DC power. |
| 2011-03-11 15:41 | 55:00 (min) | Loss of DC distribution systems resulted in the loss of control room indications and alarms. |
| | | Control room lighting lost, with only emergency lighting remaining. |
| | | Control panel indications for HPCI barely visible, but slowly faded away. Operators determined that HPCI was not operable because indicators on the control panel were lost. |
| | | RCIC manipulation lost. |
| 2011-03-11 21:13 | 6 h 27 min | TEPCO informed Government on estimated time for uncovering of the core at 21:40. |
| 2011-03-11 22:10 | 07 h 24 min | Reactor water level above TAF reported to government officials. |
| 2011-03-11 22:10 | 07 h 24 min | Radiation monitor data around plant monitoring points reported to government. |
| 2011-03-11 23:00 | 08 h 14 min | High dose rate reading in front of the Unit 1 reactor building north door on the 1st floor of the TB. |
| 2011-03-11 23:00 | 08 h 14 min | High dose rate reading in front of the Unit 1 reactor building south door on the 1st floor of the TB. |
| 2011-03-11 23:25 | 08 h 39 min | DW pressure reading. 1.41 bar |
| 2011-03-12 00:06 | 09 h 20 min | The Site Superintendent directed preparations to vent the PCV. |
| 2011-03-12 00:30 | 09 h 44 min | 3 km zone evacuation completed. |
| 2011-03-12 01:00 | 10 h 14 min | Operators sent to the RCIC room. |
| 2011-03-12 02:55 | 12 h 09 min | RCIC declared operating. |
| 2011-03-12 02:56 | 12 h 10 min | CST water level low. |
| 2011-03-12 03:06 | 12 h 20 min | Plans to vent Unit 1 and 2 PCV announced to the public. |

| | | |
|---|------------------|---|
| 2011-03-12 04:20 | 13 h 34 min | A team was dispatched to the RCIC room to manually open 3 MOVs to switch the RCIC source to SC from CST. |
| 2011-03-12 05:00 | 14 h 14 min | RCIC water intake line up to SC complete. |
| Restoration work for power supply and water injection | | |
| 2011-03-12 15:36 | 01 d 00 h 50 min | Explosion in Unit 1 occurred. |
| 2011-03-12 15:36 | 01 d 00 h 50 min | MCR lighting was lost. |
| 2011-03-12 15:54 | 01 d 01 h 08 min | Site ERC ordered the evacuation of the staff from two MCRs (Units 1 and 2 and Units 3 and 4), except for the most senior staff. |
| 2011-03-13 11:00 | 01 d 20 h 14 min | Large SC AOV is opened for venting. 3.7 bar Less than rupture disk pressure. No venting. |
| 2011-03-14 11:00 | 02 d 20 h 14 min | Alternative seawater injection line assembly completed. |
| 2011-03-14 11:01 | 02 d 20 h 15 min | Explosion in Unit 3. |
| 2011-03-14 11:01 | 02 d 20 h 15 min | Unit 3 explosion damaged seawater injection setup. |
| 2011-03-14 11:01 | 02 d 20 h 15 min | Large isolation AOV in the SC venting line closed. |
| The valve could not be reopened | | |
| 2011-03-14 13:00 | 02 d 22 h 14 min | Reactor pressure reading. 75.4 bar |
| | | Reactor water level reading. TAF+2400 mm |
| 2011-03-14 13:00 | 02 d 22 h 14 min | RCIC declared inoperable. |
| 2011-03-14 13:25 | 02 d 22 h 39 min | Time for core uncovering estimated at 16:30. |
| 2011-03-14 14:43 | 02 d 23 h 57 min | Seawater injection though core spray line re-established. |
| Vent for RV and SC was critical. SC temp. ~ Tsat | | |
| 2011-03-14 16:21 | 03 d 01 h 35 min | Unsuccessful attempt to open large isolation SC vent AOV. |

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-2

| | | |
|------------------|------------------|---|
| 2011-03-14 16:28 | 03 d 01 h 42 min | Operators decided to depressurize RPV via SRV. regardless of the concerns for PCV integrity (saturated/solid SC) |
| 2011-03-14 19:05 | 03 d 04 h 19 min | Seawater injection via fire engines commenced. |
| 2011-03-14 19:20 | 03 d 04 h 34 min | Water injection stops. Fire engines ran out of fuel |
| 2011-03-14 19:54 | 03 d 05 h 08 min | Seawater injection into RPV via FP system began. |
| 2011-03-14 21:00 | 03 d 06 h 14 min | Attempt to open small (bypass) SC vent AOV. |
| 2011-03-14 22:50 | 03 d 08 h 04 min | RPV (DW) pressure reading 540 kPa (5.4 bar) > design pressure |
| 2011-03-14 23:25 | 03 d 08 h 39 min | Discovery of small (by-pass) SC vent AOV being closed |
| 2011-03-14 23:25 | 03 d 08 h 39 min | Decision making to vent PCV directly from DW began 700 kPa |
| 2011-03-15 00:01 | 03 d 09 h 15 min | Commence opening DW vent (bypass) AOV venting did not occur |

DW pressure maintained at ~ 750 kPa until after 6 hours.


| | | |
|------------------|------------------|--|
| 2011-03-15 06:14 | 03 d 15 h 28 min | Sound of explosions at site and tremors felt in the MCR. |
| 2011-03-15 06:14 | 03 d 15 h 28 min | SC pressure dropped to atmospheric pressure. |
| 2011-03-15 06:14 | 03 d 15 h 28 min | Explosion reported in Unit 4. |
| 2011-03-15 06:30 | 03 d 15 h 44 min | SC pressure reading. 0.0 bar |

¹³⁸ Later seismic analyses by TEPCO showed that there had been no explosion inside Unit 2 and ascribed the noise to the explosion in Unit 4.

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-3

- Battery relieved flooding!



*Used for opening and closing valves in the system

Fukushima Daiichi Nuclear Disaster


❖ Severe accident at Unit-3

- Battery relieved flooding!
- Operation and control of the RCIC and HPCI could be maintained.
- It was also possible to continue monitoring reactor status using meters and gauges.
- Coolant injection continued for approximately a day and a half, after which the HPCI system was tripped to change over to injecting coolant at low pressure (with a diesel driven fire pump).
 - RPV pressure was 0.58 MPa.
 - Safety relief valve did not work due to battery run-out.
- However, depressurization after this took time, the water level dropped, and the result was the generation of hydrogen and damage to the core.


Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-3


14:46 Earthquake occurred



15:35 Tsunami hits



Water level inside the pressure vessel dropped



3/11

Cold shutdown process
in normal conditions

Cold shutdown process
in an emergency

Responses and events after the tsunami occurred

Reactor automatically trip
(scram)

Electrical power supplied
by transmission lines

Cooling by the condenser

Power provided by
generator operating
with diesel fuel
(emergency diesel generator)

Cooling with water under
high pressure (high-pressure
coolant injection)

Lower pressure of
pressure vessel
(depressurization)

Cooling continuously
with water (low-pressure
coolant injection)

Cooling (heat removal)
by the residual heat
removal system

Cold shutdown

HPCI continued
(use battery)

3/12

3/13


Switch to HPCI system
from RCIC system

Loss of cooling,
coolant injection, and
depressurization functions
(battery runs out)

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-3

About 9:25 Start coolant injection



3/14

Fuel exposure and
damage (heating while
empty conditions)

Pressure vessel damage

Container vessel damage

Hydrogen leaks
into building

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-3

| | | |
|--------------------------------------|----------------------------|--|
| 2011-03-12 11:36 | 20 h 50 min | RCIC tripped. |
| 2011-03-12 11:40 2011-03-12 12:35 | 20 h 54 min 21 h 49 min | Attempts to restart RCIC unsuccessful. HPCI started. |
| 2011-03-12 12:45 | 21 h 59 min | Reactor pressure. 5.6 MPa |
| 2011-03-12 17:00 | 01 d 02 h 14 min | Reactor pressure. 2.9 MPa |
| 2011-03-12 19:00 | 01 d 04 h 14 min | Reactor pressure reading. 0.95 MPa |
| 2011-03-13 02:30 | 01 d 11 h 44 min | Reactor pressure reading. 0.79 Mpa, Below the set point of the automatic isolation of the HPCI. |
| 2011-03-13 02:30 | 01 d 11 h 44 min | HPCI fails to auto stop. |
| 2011-03-13 02:30 | 01 d 11 h 44 min | Decision to switch core cooling function from HPCI to DDFP. |
| 2011-03-13 02:30 | 01 d 11 h 44 min | Team dispatched to reactor building to switch DDFP line up to RPV injection from SC spray. |
| 2011-03-13 02:42 | 01 d 11 h 56 min | DDFP line up was changed from SC spray to RPV injection. |
| 2011-03-13 02:42 | 01 d 11 h 56 min | HPCI stopped. |

Due to the possibility of reactor pressure drop causing a further slowing of HPCI turbine revolution speed, which would increase turbine vibrations and ultimately result in reactor steam release due to equipment damage.

Fukushima Daiichi Nuclear Disaster

❖ Severe accident at Unit-3

| | | |
|------------------|------------------|--|
| 2011-03-13 02:44 | 01 d 11 h 58 min | Reactor pressure reading. 0.58 MPa |
| 2011-03-13 02:45 | 01 d 11 h 59 min | Attempt to open SRV unsuccessful. |
| 2011-03-13 03:00 | 01 d 12 h 14 min | Reactor pressure reading. 0.87 MPa |
| 2011-03-13 03:05 | 01 d 12 h 19 min | Attempt to inject water via DDFP unsuccessful. |
| 2011-03-13 03:35 | 01 d 12 h 49 min | Attempt to restart HPCI. |
| 2011-03-13 03:37 | 01 d 12 h 51 min | Attempt to restart RCIC. |
| 2011-03-13 03:37 | 01 d 12 h 51 min | Team dispatched to HPCI room to local manual start of HPCI. |
| 2011-03-13 03:38 | 01 d 12 h 52 min | Attempt to open SRV unsuccessful. |
| 2011-03-13 03:39 | 01 d 12 h 53 min | Operators start load shedding of HPCI equipment to preserve DC power. |
| 2011-03-13 03:44 | 01 d 12 h 58 min | Reactor pressure reading. 4.1 MPa |
| 2011-03-13 03:51 | 01 d 13 h 05 min | Reactor water level monitor restored. |
| 2011-03-13 03:51 | 01 d 13 h 05 min | Reactor water level reading. |
| 2011-03-13 04:30 | 01 d 13 h 44 min | Reactor pressure reading. 7.0 MPa |
| 2011-03-13 05:08 | 01 d 14 h 22 min | Attempted to restart RCIC. |
| 2011-03-13 09:08 | 01 d 18 h 22 min | Reactor pressure decreased. |
| 2011-03-13 09:10 | 01 d 18 h 24 min | Increased SC pressure. |
| 2011-03-13 09:20 | 01 d 18 h 34 min | Unit 3 PCV venting. |
| 2011-03-13 09:25 | 01 d 18 h 39 min | Borated freshwater injection into the reactor started through the FP line. |

The SRVs did not open, although the valve status in the MCR displayed them as functional. It is considered that the **battery capacity was enough to display the status indicator lamps, but not enough to operate the SRVs.**


Fukushima Daiichi Nuclear Disaster

❖ Hydrogen explosion at Unit-4


The moment the tsunami struck

Stack

Reactor building (Unit 3)




Reactor building (Unit 4)



Fukushima Daiichi Nuclear Disaster

❖ Hydrogen explosion at Unit-4


Inflow route of hydrogen into Unit 4




Fukushima Daiichi Nuclear Disaster

❖ Hydrogen explosion at Unit-4

14:46 Earthquake occurred




15:35 Tsunami hits



Power lost due to tsunami
Coolant functions and ability to resupply water lost

Rise of water temperature in spent fuel pool



The water temperature of the spent fuel pool confirmed to be 84°C; fuel forecast to be exposed above the water's surface in late March.

3/11

Cooling process in normal conditions

Heat removal with the make-up water condensate system of the pool

Injecting coolant via fuel pool cooling and filtering system


Total power failure

3/13~

3/15

3/20


Responses and events after the tsunami occurred



Hydrogen inflow from Unit 3



Around 6:14 a.m. Hydrogen explosion in the Unit 4 reactor building



8:21 Begin injecting coolant into spent fuel pool

Fukushima Daiichi Nuclear Disaster

❖ What if?


- Easy to say “if IC were not terminated”; “if RCIC and HPCI were not stopped manually”, ... , etc.
- These afterthoughts are not totally correct.
- True that the reactor core seemed to have survived as long as IC or RCIC/HPCI were operating but this does not mean that the core could avoid core damage and melting w/o heat sinks.

Fukushima Daiichi Nuclear Disaster

❖ Magnification of damage

- Due to simultaneous accidents at Units 1~4


Simultaneous problems at four units




In this way, one of the lessons learned from the events is that the progression of the accident at one unit had a big impact on restoration work at the other units.

❖ Development of Fukushima Daiichi accident

Summary of developments at each unit





Simultaneous problems at four units



Fukushima Daiichi Nuclear Disaster

❖ Fukushima Daini vs. Daiichi



12 m above sea level




Fukushima Daiichi Nuclear Disaster

❖ Future responses

Mid-and-Long Term Roadmap for Fukushima Daiichi Nuclear Power Station

(announced December 2011)



❖ Current status

- <https://www.tepco.co.jp/en/insidefukushimadaiichi/index-e.html>

Fukushima Daiichi Nuclear Disaster

❖ Future responses




“The current situation at Fukushima Daiichi NPS”
From 3.II towards the future

ver. January 2020


Fukushima Daiichi Nuclear Disaster

❖ Current status




Fukushima Daiichi Nuclear Disaster

❖ Current status






Fukushima Daiichi Nuclear Disaster

❖ Reactor Circulation Cooling




Fukushima Daiichi Nuclear Disaster

❖ Ground water




Fukushima Daiichi Nuclear Disaster

❖ Reactor Circulation Cooling



Fukushima Daiichi Nuclear Disaster

❖ Reactor Circulation Cooling



Fukushima Daiichi Nuclear Disaster

❖ Reactor Circulation Cooling <https://www.youtube.com/watch?v=o0cwp-d5BSU>

