

Lecture 4:

MEMS fabrication II: surface micromachining (1)

- p19

Velocity is as large as good, but flow should be laminar because of uniformity. Therefore, maximum proper velocity could be obtained.

- p24

It is favorable to performed in high temperature, low pressure but cost problem should be considered.

- p33

It can be performed at low temperature but quality of layer is also low!!!