2017 Fall

"Phase Transformation in Materials"

09.04.2017

Eun Soo Park

Office: 33-313 Telephone: 880-7221 Email: espark@snu.ac.kr Office hours: by an appointment

1

Introduction

- Web lecture assistance: http://etl.snu.ac.kr
 - All materials will be posted at the webpage.
 - text message will be sent for the important and urgent notice.
- Hand out copied materials or scanned materials in website

Text: "Phase Transformations in Metals and Alloys",

D.A. Porter and K.E. Eastering, Chapman & Hall

Prerequisite coursework: Materials Science and Engineering, Thermodynamics

References: 1) "Diffusion in Solid," Paul G. Shewman, TMS (1989)

2) "Physical Metallurgy Principles," Reed-Hill, PWS–Kent (1992)

Additional reading materials will be provided.

Course Goals

presents a unified treatment of This the course thermodynamics and kinetics of phase transformations from phenomenological and atomistic viewpoints. Phase transformations in condensed metal and nonmetal systems will be discussed. This course begins with reviewing the principles of thermodynamics, phase equilibriums, diffusion, and crystal interfaces. The topics include absolute reaction rate theory, thermodynamics of irreversible processes, thermodynamics of surfaces and interfaces, chemical kinetics, nucleation and spinodal decomposition, growth, order-disorder transformations, diffusional transformations, martensitic transformations, coarsening, and glass transition. By the end of the semester, you will be able to understand key concepts, experimental techniques, and open questions in the transformation phenomena of various materials.

Schedule

- week 1 Introduction to phase transformation
- week 2 Equilibrium single component system/ Binary solutions
- week 3 Binary phase diagram
- week 4 Ternary phase diagram
- week 5 Atomic mechanism of diffusion/ Interstitial diffusion
- week 6 Substitutional diffusion/ Atomic mobility/ Diffusion in alloy
- week 7 Interfacial free energy/ Solid/vapor interfaces
- week 8 Boundaries in single-phase solids/ Interphase interfaces in solids
- week 9 Interface migration/ Mid-term exam
- week 10 Nucleation in pure metals
- week 11 Growth a pure solid/ Alloy solidification
- week 12 Solidification of ingots and casting
- week 13 Nucleation/ Precipitate growth/ Precipitation in age-hardening alloys
- week 14 Various diffusional transformation in solids
- week 15 Diffusionless transformation Martensite transformation
- week 16 Team project presentation & Final exam

Contents of this course_Phase transformation

Background to understand phase transformation (Ch1) Thermodynamics and Phase Diagrams(Ch2) Diffusion: Kinetics(Ch3) Crystal Interface and Microstructure

Representative Phase transformation (Ch4) Solidification: Liquid → Solid

(Ch5) Diffusional Transformations in Solid: Solid \rightarrow Solid

(Ch6) Diffusionless Transformations: Solid → Solid

Components of Your Grade:

1) Exams (mid-term: 35% + final: 40%)

There will be two exams, each of which will take 2-3 hours. I will not use class time for the exams and instead will reserve separate time slots.. The exams will be conceptual and difficult.

2) Team project (15%)

Course participants will organize into small groups. Topics for phase transformation will be discussed, and each group will submit a proposal and reports as well as give a final presentation.

3) Homework (5%) (+Incentive Homework 5%) and Attendance (5%) Assignments handed in after the start of class lose credit depending on the timing. If you wish, you may work together on homework assignments. But, you must hand in your own work, in your own words.


Remarks:


1) The weight of each component above could be adjusted up to 5% based on students' performance. 2) Student who retakes this course will have their final scores adjusted downward by 5% in order to ensure fairness with other students.

Policies and Procedures

- All homework are due by the start of class on the stated deadline.
 - Late assignments go to my office. If I'm not around, slide it under my door and leave me an email so that I know when you turned it in.
 - You lose 20% of the full assignment value per day late. Since homework are due on Wednesday, you can get 80% credit if you turn it in on Friday, 50% on next Wednesday, nothing thereafter.
- If you wish, you may work together on homework assignments. BUT, you must hand in your own work, in your own words.
- IMPORTANT: you MUST reference your sources appropriately, including texts, journals web sites, etc.
 - Article authors, title, journal, volume, year, pages
 - Book authors, title, publisher, year, pages
 - Web address
 - etc.

Microstructure-Properties Relationships





Q1: What is alloy design? "Materials selection"

1) Alloy design: a. Materials selection

One of the Most Popular Structural Materials ; Iron-Carbon Alloy (or Steel)



Steel frame of building

1) Alloy design: Materials selection \implies b. Change of alloy compositions

Application of Iron-Carbon Alloy

K1 – main battle tank of Korea army



Need of the strongest materials

1) Alloy design: Materials selection \implies c. Change of alloy system

Dominant Material for Airplanes ; Aluminum Alloy

B737-800 of Korean Air



Need of light, strong and tough material


Q2: How to classify material depending on the structure?


2) Classification of Material depending on the structure

Structure of crystals, liquids and glasses

Crystals

Liquids, glasses






- periodic
- grain boundaries

amorphous = non-periodic no grain boundaries

Atomic structure




Q3: What are phase, phase diagram and phase transformation?

3) Microstructure control

: Equilibrium phase → Only consider Thermodynamics ① What is Phase?

A phase is a chemically and structurally homogeneous portion of the microstructure. (structure or composition or order)




Microstructure control

: Equilibrium phase

Only consider Thermodynamics

2 Phase Diagram of Temperature – Composition ;

most useful in materials science & engineering



Microstructure control : Phase transformation 👄 **Atomic Migration** ③ Phase Transformation of Iron and Atomic Migration T(°C) Liquid Gas Liquid Temperature 1538 1394 **Face-Centered Cubic** δ γ (austenite) Y 910 **Atomic Migration** α (ferrite) α

at 1 atm

Pressure (log scale)

1 atm

Body-Centered Cubic

20

Q4: What is microstructure?

4) What is microstructure?


Microstructure originally meant the structure inside a material that could be observed with the aid of a microscope.

In contrast to the crystals that make up materials, which can be approximated as collections of atoms in specific packing arrangements (crystal structure), microstructure is the collection of defects in the materials.

What defects are we interested in?
 Interfaces (both grain boundaries and interphase boundaries), which are planar defects,
 Dislocations (and other line defects), and
 Point defects (such as interstititals and vacancies as well as solute atoms in solution)

* Imperfection: Grain Boundaries

(Planer defect)




Q5: How to control the microstructure by process control?

5) Microstructure control


: process control after materials selection **→** property optimization

A Example of ① Grain Boundary Engineering ; Turbine blade in Aircraft Engine




5) Microstructure control : 2 Secondary phase control


a. Phase Diagram of Iron–Carbon Alloy



5) Microstructure control : 2) Secondary phase control b. Equilibrium Phases of Iron-Carbon Alloy




5) Microstructure control : 2 Secondary phase control



c. Mechanism of Precipitation

5) Microstructure control : 2) Secondary phase control

d. Effect of Second Phase Particle on Mechanical Property




29

5) Microstructure control : 2) Secondary phase control

e. Control of Microstructures by Precipitation Transformation in Aluminum Alloy

Boeing 767 by AA7150 T651 alloy



Q6: How to optimize microstructure by process control?

6) Microstructure optimization by process control

① Cold Work_ 압력을 가해 성형하고 인성을 증가시키는 과정

김홍도 "Smithy_대장간"


Joseon Dynasty



Modern forging machine


6) Microstructure optimization by process control

Hardening Mechanism by Cold Working




6) Microstructure optimization by process control

Changes of Strength and Ductility by Cold Working



6) Microstructure optimization by process control 2) Changes of Microstructure & Mechanical Properties during Annealing



내부 변형률 에너지 제거 낮은 전위밀도 (변형률이 없는) 결정립

35

Q7: How to optimize material property? "Alloy design + Process control"

7) Alloy design + Process control Property optimization

e.g. Production and Application of Electrical Steel

Hot rolling - cold rolling – 1st annealing – 2nd annealing





Stacked transformer core

Transformer Motor Etc.

Soft magnetization property



Microstructural Parameters vs Properties

Properties

- Strength
- Toughness
- Formability
- Conductivity
- Corrosion Resistance
- Piezoelectric strain
- Dielectric constant
- Magnetic Permeability

Microstructural Parameters

- Grain size
- Grain shape
- Phase structure
- Composite structure
- Chemical composition (alloying)
- Crystal structure
- Defect structure (e.g. porosity)

Alloy design + Process control → Microstructure Control of Materials




Better Material Properties

Important!!!

8) Understanding and Controlling Phase Transformation of Materials

Q8: How to control the phase transformation? "Thermodynamics + Kinetics"



How does thermodynamics different from kinetics?

Thermodynamics \rightarrow There is no time variable.

says which process is possible or not and never says how long it will take. The existence of a thermodynamic driving force does not mean that the reaction will necessarily occur!!!






Allotrope (同質異像): any of two or more physical forms in which an element can exist 화학성분 같고 결정구조 다름

There is a driving force for diamond to convert to graphite but there is (huge) nucleation barrier.

How long it will take is the problem of kinetics. The time variable is a key parameter.



➡ Governed by Thermodynamics & Kinetics

Q9: What are the representative PTs?

9) Representative Phase Transformation

- Solidification: Liquid ight Solid
- Phase transformation in Solids
 - ① Diffusion-controlled phase transformation ; Generally long-distance atomic migration
 - Precipitation transformation
 - Eutectoid transformation (**S > S**1 **+ S**2)


- etc.

② Diffusionless transformation ;


Short-distance atomic migration

- Martensitic transformation

1 Diffusion-controlled phase transformation




Transformation Kinetics : b. Isothermal Transformation Diagram




TTT diagram Isothermal transformation diagram

c. Isothermal Transformation Diagram of a Eutectoid Iron-Carbon Alloy



Microstructure control by phase transformation

d. Control of Phases by Heat Treatment



e. Control of Mechanical Properties by Proper Heat Treatment in Iron-Carbon Alloy



Martensite


Tip of needle shape grain

Nucleation site of fracture

Process control



Proper heat treatment (tempering)



Tempered martensite



Very small & spherical shape grain


Good strength, ductility, toughness




② Diffusionless Transformation

Individual atomic movements are less than one interatomic spacing.

e.g. a Martensitic transformation in iron-carbon alloy



Principles - Shape memory process






- 1. A_f 이상의 온도로 열처리를 통해 Austenite 상에서 형상 기억
 - 2. M_s 이하의 온도로 냉각시 Twinned martensite 생성
- 3. 항복강도 이상의 응력을 가하면 Twin boundary의 이동에 의한 소성 변형
- 4. A_f 이상으로 가열해주면 martensite 에서 다시 Austenite로 변태
- ➡ 기억된 형상으로 회복

" $\gamma \leftrightarrow M$ transformation: Short-distance atomic migration "

Microstructure-Properties Relationships



53

Q10: What are the contents of this course?

10) Contents of this course_Phase transformation

Background to understand phase transformation (Ch1) Thermodynamics and Phase Diagrams (Ch2) Diffusion: Kinetics

(Ch3) Crystal Interface and Microstructure

Representative Phase transformation (Ch4) Solidification: Liquid \rightarrow Solid

(Ch5) Diffusional Transformations in Solid: Solid \rightarrow Solid

(Ch6) Diffusionless Transformations: Solid → Solid